

Medford Service Center, Warehouse (Bldg. #2203) HAER No. OR-160-A
1319 East McAndrews Road
Medford
Jackson County
Oregon

HABS
ORE
15-MED,
1A-

PHOTOGRAPHS

Historic American Engineering Record
National Park Service
Western Region
Department of the Interior
San Francisco, California 94107

HABS
ORE
15-MED
1A-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Medford Service Center, Warehouse (Building #2203)
1319 McAndrews Road
Medford
Jackson County
Oregon

HABS No. OR-160-A

Natalie Brown, Photographer

April 1993

- OR-160-A-1 VIEW OF WEST SIDE AND SOUTH (REAR) SIDE OF WAREHOUSE (BUILDING #2205), FACING NORTHEAST.
- OR-160-A-2 VIEW OF NORTH FRONT AND WEST SIDE OF BUILDING #2205 (AREA CONTAINING STORAGE AND EQUIPMENT SUPPLIES), FACING SOUTHEAST.
- OR-160-A-3 VIEW OF EAST SIDE AND NORTH FRONT OF BUILDING #2205 (AREA CONTAINING VEHICLE REPAIR SHOP AND VEHICLE MANAGEMENT OFFICE), FACING SOUTHWEST.
- OR-160-A-4 BUILDING #2205, INTERIOR VIEW OF VEHICLE REPAIR SHOP, FACING SOUTHEAST.
- OR-160-A-5 BUILDING #2205, INTERIOR VIEW OF UPPER STORAGE FLOOR ("ATTIC") SHOWING SKYLIGHT, FACING SOUTHEAST.
- OR-160-A-6 BUILDING #2205, INTERIOR VIEW OF UPPER STORAGE FLOOR ("ATTIC") SHOWING LIGHT ADMITTED BY MAIN BANK AND UPPERMOST WINDOWS, FACING SOUTHWEST.
- OR-160-A-7 BUILDING #2205, INTERIOR VIEW OF UPPER STORAGE FLOOR ("ATTIC") SHOWING FREIGHT ELEVATOR, FACING WEST-NORTHWEST.

Note: All photographs are 8" x 10" enlargements from 4" x 5" negatives.